## Replace MAC Automatic Regulator with SMC

## 1. Tubing






Connect Tube at "IN" on MAC to "1 SUP" on SMC





Connect Tube at "EXH" on MAC to "3 EXH" on SMC





Connect Tube at "OUT" on MAC to "2 OUT" on SMC

## 2. Wiring

On the SMC cable connect:

Brown Wire to 24VDC Blue Wire to 0VDC White Wire to A1 Black Wire not used

## 3. Calibration

The unit is calibrated at the factory. If it needs to be adjusted follow these steps

- Hold "UNLOCK" button until "LOC" flashes on display
- Press "S" button until "unL" appears
- Press "S" button twice until "F\_2" appearsUse the Arrow Up (Lock) and Arrow Down (Unlock) buttons to adjust the MAX pressure
- For ServoJet / ServoSpray / ServoSonic set to 50psi.

Confirm that the Analog Control Voltage is correct. Set the tank pressure to 25psi on the machine software. With a voltmeter set to DC Volts, measure the voltage between A1 and 0V.

25 psi = 5.0 V50 psi = 10.0 V

